

Order No.: DD+DIS217.02E



1 piece VE2WD MA1

ADC Solo
Type 5155 / 100

Centricity CR SP1001
Type 5155 / 200

Rating			When?		
safety relevant	reliability	new function	immediately	next service	as required
	X			X	

Please file this document in section 13 of your technical documentation

Modification kit “C-clips Protection and Discharge Plate” applied to ADC Solo

1 Modification kit “C-clips protection and Discharge plate”

Order number: CM+9.5146.9040.0

1.1 Scope of Delivery

4 x C-clip protection plates

4 x Screws

1 x Discharge plate

1 x Installation Instructions DD+DIS109.02E



For ADC Solo only two of the four C-clips protection plates are needed. Discharge plate is not applicable for ADC Solo. It only has to be installed in ADC Compact.

1.2 Modification “C-clips protection”



This is a must-modification! C-clips protection plates avoid imprudent removal of scan rollers.

Incorrect reinsertion of scan rollers after cleaning causes broken c-clips and therefore a replacement of the complete slow scan unit is necessary. To avoid removal of scan rollers modification “C-clips Protection Plate” is introduced.



Protection plate has to be installed with the crank towards the scan roller. Install c-clips protection plates only on the upper rollers.



Do not remove lower rollers for cleaning purposes! This can be done by turning the clutch.